

WATER AND FLOOD RISK

- A large monitoring network of boreholes and gauges was established over 20 years ago and further monitoring points have been added.
- Protective measures will involve the use of clay barriers around the workings and recharge trenches, which have a successful proven track record at Gill Mill in maintaining water levels.
 - A comprehensive flood risk assessment is being undertaken.
- The site area is largely out of the flood zone.

